

Extruder Mount

M3 bolt fits all holes on the bottom

M4 bolts fit two holes for extruder

No warping

No skew

Thermal inserts go in outer four vertical holes

No eggy holes

Visual check

