

Power Supply Cover

No Warping (highly visible part)

No Z-wobble

No Skew (all corners are square)

Top three holes need to fit M4 bolts

The two circles next to the large square hole are for thermal set inserts

The four holes on the side need to have zip-ties fit through

