

### Y-idler Mount

No warping

Bottom of part is the front face of the printer

Minimal bubbles

10mm rod needs to fit two 10mm holes snugly

M5 bolts need to fit all extrusion mounting holes

M8 bolt needs to fit in the idler carrier

Thermal sets go in perpendicular to 10mm holes

Visual check

