

Z-Motor Mount

0 Warping

Clean outer surfaces

Small bubbles ok, bottom surface not visible on one side, faces out on other side

No Z wobble

No skew

M5 bolt needs to fit outer four horizontal holes

Thermal insert goes into endstop holder

M3 bolt needs to fit in motor mount holes

10 mm rod needs to fit in two 10mm holes cleanly

Endstop goes into horizontal square hole

Visual check

