

## Z Nut Spring M6

Clean print surface

M3 thermal inserts go into four horizontal holes

No banding on through hole layers

No warping

No Z wobble

Support can be broken out with a flat-head screwdriver, then cleaned with an x-acto blade

M6 nut needs to fit inner hex-hole

Minimal blobs, visible part

RAM intensive print

Visual check

