

# CUSTOMER CHANGE NOTICE

1001 25th St N Fargo ND 58102 • +1-701-809-0800 x2 • Support@LulzBot.com

## M175 Tool Head Update

The newest LulzBot firmware (Cura LE 3.6.30 and higher) is not compatible with the M175 v1. This new firmware features two large improvements to many models:

- **Universal Tool Head swapping without having to reflash firmware**
- **An Improved Bed Leveling Algorithm**

To allow users to easily update we created the [M175 v2 conversion kit](#).


This modifies the mounting location in order to take advantage of these firmware improvements.

See below to identify the **M175 v2** to check if you require updating:

*M175 v1 Front*




*M175 v1 Side*



*M175 v2 Front*



*M175 v2 Side*



Installation Instructions



With this change, the M175v2 has different part numbers for the extruder mount(PP-GP0498) and the blower shroud(PP-GP0497).

M175 v1 to M175 v2 conversion kit will be provided for free through **January 31, 2022**.

If you need help or have any issues, please email [support@lulzbot.com](mailto:support@lulzbot.com)