

Enclosure Bottom

No warping

M5 bolt fits inner four vertical holes

M3 bolt fits outer four vertical holes and three horizontal holes on strain relief

Thermal inserts go in inner four partial vertical holes

No skew

Clean outer surfaces, top surface faces inside of enclosure

Visual check

