

### Enclosure Power Cord Side

No warping

Vertical holes are clean/not eggy

Part is square

All horizontal holes are for M3 thermal inserts

Four holes around power socket mount are for M3 thermal inserts

Bottom surface faces back of the machine

Top layer faces inside of case

Visual check

