

Enclosure Strain Relief Bar

M3 Thermal inserts go in all three holes

No warping

Entire part is not visible on finished machine, goes inside enclosure

Visual check

