

Extruder Latch

No warping

Wipe off blobs

M4 bolt needs to fit both holes

No skew

Visual check

