

Frame Connector

Make sure corner is square/no skew in the print

No warping

M5 bolt fits all holes

Visual Check

