

Large Herringbone Gear

0 Warping

0 Blobs in teeth

0 Z wobble

One of the most important printed parts on the machine!

M8 bolt needs to fit center hole

Visual check

