

X-carriage

No warping

No skew

No bubbles on bottom surface

No egg holes

M3 needs to fit all smaller round holes

Thermal inserts for all other round holes

Clean belt clamp gap with knife

