

X-carriage Guide

M3 bolt fits all four holes

No warping

Clean surfaces

No bubbles in print surface(faces toward front of machine)

No skew

Visual check

