

## Y-belt Mount

No warping

Thermal inserts go into all eight holes

No banding on layers with horizontal holes

Can have bubbles (goes on y bed plate)

Visual check

