

Y-mount Chassis

No skipped steps(can be easy to miss)

No warping

Only prints well on nicely calibrated machines

M5 bolt needs to fit both the slotted hole on the bottom and the horizontal hole

No Z wobble

Visual check

