Z-top

No warping
M5 bolt needs to fit outer eight holes
10mm rod needs to fit 10mm hole snugly
No skew in the print
No bubbles(bottom surface is top of the printer
Clean outer surfaces
No eggy holes
Visual check

