## Double Bearing Holder


Back needs to stay straight with bearing inserted Needs to be printed on well calibrated machines

No banding on the through-hole layers

No warping or Z wobble

All holes should fit an M3

Test for binding by inserting both bearings then sliding 10mm rod through,



ว์ mm