Enclosure Switch Side

No warping

Outer four holes should fit M3 bolts

No skew

Clean outer surfaces

Bottom surface is the top of the enclosure Top layer is not visible, faces inside of the machine

Visual check

