


Extruder Idler

No warping

Drill two horizontal holes to 3.5mm

608 bearing goes in 8mm x 20mm rod in middle groove

Visual check



Extruder Washer

Needs to fit bottom bearing holder on extruder body

Can have edges cut/trimmed to fit, non-visible part

Visual check