PP-MP0231: Bottom Plate, Quiver

Oliver Darling

November 7, 2018




Figure 1: Schematic of PP-FP0154.

1 Dimensions



Figure 2: Dimension 01.



Figure 3: Dimension 06

To find the critical dimensions of this part all we need is a set of calipers. Important to note that when taking the distance from a hole, as seen in Figure [3], we need to make sure we remember to add the radius of each hole that we are referencing.

Item	Dimension	Tolerance	Mean	Fallout Rate
Dim01	34.5	± 0.75	34.49	0%
Dim02	18.8	± 0.75	18.75	5.49%
Dim03	6.4	± 0.75	6.37	0%
Dim04	5.4	± 0.75	5.40	0%
Dim05	12.43	± 0.25	12.42	1.81%
Dim06	23.5	± 0.25	23.48	0%
Dim07	Ø6	+0.125	6.05	4.25%
	00	-0.0	0.05	4.2070
Dim09	11.6	± 0.75	11.59	0%
Dim15	23.2	± 0.75	23.23	0%